

**Name:** Apenisa Naigulevu

**DOB :**13.08.1957

**Disability:** Spinal Cord Injury

**Need Request:** Wheelchair Accessible Ramp

**Contact:** Mobile – 2858615 / 2708954



---

In 2012, Apenisa Naigulevu (65) was injured when he fell into their dug septic tank hole about 6ft deep. He suffered from neck injury resulting in his paralysis.

Naigulevu requested completion to his flooring on the verandah/porch area and install railings as its above the ground. The Habitat constructed the verandah/porch area with poor workmanship. It was incomplete and exposed Apenisa to danger with no safety railings.

Scope of Works:

1. Marking
2. Preparation of site for construction
3. Structure
4. Flooring
5. Installation of railings
6. Painting works
7. Miscellaneous Works
8. Clean Up work area

Tabulated below breakdown of funding:

Project: commencement: 26.10.22

Project completed of project:28.10.22

Gallery :



Apenisa Naigulevu filling out his ID Form after being interviewed and assessed.

Men at work



Assistant Project Completed



